


A fresh start for the back deck.

COMPLETED	2026-09-05
PREPARED FOR	Sample customer
LOCATION	Illustrative project - not an actual job

AFTER



Refinished boards with a warm protective finish. Illustration.

Work completed

Cleaned and refinished the deck boards. Replaced damaged timber and applied a warm, protective finish.

This sample uses original illustrations to demonstrate the report layout. Your report will feature the photos and descriptions you provide.

PHOTO DOCUMENTATION

BEFORE



Weathered boards before cleaning and restoration. Illustration.

PREVIEW